

CONTRACTOR VERIFICATION SHEET

ELEVATOR DESIGNATION: EV1

FACTORY JOB NUMBER:

REQUIRED CAB INFORMATION:

CAB WALL COLOR:	Select Cherry 7759	▼
CAB CEILING FRAME FINISH COLOR:	Smoked Silver F-131	▼

REQUIRED ENTRANCE INFORMATION:

MAIN EGRESS/ FIRE RECALL @ FLOOR MARKED: 1

FLOOR MARKING:	WALL TYPE:	WALL THICKNESS (X):	ENTRANCE DOOR FINISH:	ENTRANCE FRAME FINISH:
2	Concrete	9 1/8"	#4 STAINLESS STEEL	#4 STAINLESS STEEL
1	CMU - DETAIL		#4 STAINLESS STEEL	#4 STAINLESS STEEL

REQUIRED POWER CONFIRMATION:

WE REQUIRE THAT THE FOLLOWING POWER INFORMATION BE CONFIRMED:

BUILDING POWER: 208 VOLTS A.C., 3 PHASE, 60 CYCLES ☒ CONFIRMED

STARTING TYPE: SOLID STATE STARTING

☐ CORRECTED: VOLTS: _____ PHASE: _____ CYCLES: _____

EMERGENCY POWER VERIFICATION:

IS EMERGENCY OPERATION ON BUILDING GENERATOR POWER REQUIRED?

☐ YES ☒ NO

IF YES, HOW MANY ELEVATORS WILL BE CAPABLE OF RUNNING AT THE SAME TIME WHILE ON EMERGENCY POWER ? _____

FOR MR AND GR VERSIONS OF CONTROLLERS ELECTRICAL CONTRACTOR MUST PROVIDE:

- AUXILIARY CONTACTS IN THE DISCONNECT.

- IF EMERGENCY POWER IS PROVIDED, THEN EPP CONTACTS FOR CONTROLLER ARE REQUIRED.

NOTE: IF CONTROLLER IS JAMB MOUNTED THEN THE AUXILIARY CONTACTS ARE INCLUDED WITH THE DISCONNECT IN THE CONTROLLER. SEE LOCAL Thyssenkrupp FIELD REPRESENTATIVE FOR MORE INFORMATION.

MATERIAL RELEASE FORM:

In an effort to meet your expectations concerning schedule for the project, we are requesting material delivery/start dates based on the availability or anticipated completion of the items listed in the Thyssenkrupp site binder.

Note: Prior to the delivery of material and the start of installation, all items on the pre start check list inside the thyssenkrupp elevator site binder must be completed.

Requested Elevator Material Delivery/Start Date: 11 / 1 / 21

(Delivery of all remaining material, less any early shipment)

The General Contractor agrees to assume responsibility of the equipment the day of arrival from the factory on date mentioned above. Adequate ingress and egress to this area must also be provided along with a dumpster or area for disposing of packaging material. Any relocation of the equipment as directed by the contractor/owner after its initial delivery will be at others (not thyssenkrupp elevators) expense.

If the site conditions are not in place at the time of elevator delivery, the equipment will be stored per the rates established in the contract and the thyssenkrupp elevator proposal. At such time the site becomes ready for delivery/starting the elevator installation, thyssenkrupp will need payment of any outstanding invoices inclusive of storage costs accrued before delivery/mobilization and in the thyssenkrupp elevator proposal for storage fees.

CUSTOMER APPROVAL BOX

(PLEASE ITEMS MUST BE COMPLETED BEFORE THE ELEVATOR WILL BE MANUFACTURED)

NET TRAVEL: <input checked="" type="checkbox"/> CONFIRMED AS SHOWN ON SECTION VIEW	CLEAR <input checked="" type="checkbox"/> CONFIRMED AS SHOWN ON SECTION VIEW
OVERHEAD: <input type="checkbox"/> CORRECTED: _____	CORRECTED: _____
PIT <input checked="" type="checkbox"/> CONFIRMED AS SHOWN ON SECTION VIEW	HORISTWAY <input checked="" type="checkbox"/> CONFIRMED AS SHOWN ON SECTION VIEW
DEPTH: <input type="checkbox"/> CORRECTED: _____	SIZE: <input type="checkbox"/> CORRECTED: _____
HAND OF <input checked="" type="checkbox"/> CONFIRMED AS SHOWN ON SECTION VIEW	FIRE SERVICE <input checked="" type="checkbox"/> PRIMARY SERVICE AT FLOOR: 1
DOOR: <input type="checkbox"/> CORRECTED: _____	LOCATION: <input type="checkbox"/> ALTERNATE SERVICE AT FLOOR: _____

DESCRIPTION OF YOUR CAB FEATURES:

CAB TYPE:	FLAT PLASTIC LAMINATE WALLS (TCLP)
CAB CEILING:	SUSPENDED CEILING WITH LED LIGHTING
CAB DOOR:	#4 STAINLESS STEEL
CAB SILLS:	ALUMINUM
CAB HANDRAIL(S):	(1) 1/4" X 2" CONTINUOUS FLAT BAR
HANDRAIL(S) FINISH:	#4 STAINLESS STEEL
CAB PROTECTION:	PAD BUTTONS PROVIDED, (1) PADS
CAB FLOORING:	CARPET OR VCT (3/8" MAX. THICKNESS) BY OTHERS

FEATURES FOR YOUR FIXTURES:

PUSH BUTTON ILLUMINATION COLOR: BLUE

ENTRANCE WALL DETAIL



APPROVED BY: _____

DATE: _____

FAILURE TO FULLY COMPLETE THIS SHEET MAY RESULT IN DELAY OF SCHEDULE

6 - 9 - 21